

HAZARDOUS MATERIALS ASSESSMENT OF HOUSING UNITS AT CFB GAGETOWN OROMOCTO, NEW BRUNSWICK



OCL Group was retained to develop and implement a hazardous materials assessment of 155 housing units slated for demolition. The results of the survey were to be used to guide contractors in appropriate demolition management and for worker protection. The housing units had been constructed in the early and mid-1950's. Issues to be addressed included: PCB in light ballasts, asbestos-containing materials, furnace fuel oil tanks, mercury in thermostats, haz chemicals (paints and solvents) and building materials.

Client: ARC/Gecobac on behalf of Canadian Forces Housing Authority.

